

BEWARE OF "BARGAIN" DENTISTRY

These "fillings" were done in another country in order to save money.

As you can see, there is a large gap between the teeth and the dentist left a piece of the old amalgam filling in place on the tooth on the left.

